



INSPECTION CERTIFICATE N° 465

BV Job Nr: IDD.TR.1917609.14.A11.Rev01

PROJECT: Load test of Pelisafe Safe Façade Scaffolding System .	Ref: IDD.TR. 1917609.14.A11
BV Client: Pelit İnşaat Kalıp Sistemleri San. ve Tic. A.Ş.– İst./TUR.	P/o nr: N/A (client to BV)
Manufacturer: Pelit İnşaat Kalıp Sistemleri San. ve Tic. A.Ş.– İst./TUR.	P/o nr: N/A (client to Manufacturer)
Inspection requested by: Pelit İnşaat Kalıp Sistemleri San. ve Tic. A.Ş.– İst./TUR.	

SUPPLY / SUBJECT OF INSPECTION	ITEM / TAG Nr	QTY
Witness of Load Test of Pelisafe Safe Façade Scaffolding System .- according to TS EN 12810- TS EN 12811.	Pelisafe Safe Façade Scaffolding System	1 Set

Scope of inspection:

- Load Test of Pelisafe Safe Façade Scaffolding System were Performed According to TS EN 12810 and TS EN 12811. Test results were satisfactory.
- **Reference documents used for inspection:** TS EN 12810- TS EN 12811.and Technical data of Pelit AŞ.
- **Place of inspection & date or period:** ISTANBUL – April 02-04. 2015
- **Marking and stamping:** No.
- **Annexes to this certificate:** Insp.Report of BV and Bogaziçi Üni.Test Report for Pelisafe Safe Façade Scaffolding System.
- **Related IR No:** IR: 1358

The undersigned, inspector to Bureau Veritas, certifies that the hereabove mentioned supply was inspected in conformity with the applicable requirements of the purchase order and the contractual requirements governing the mission entrusted to Bureau Veritas without any remarks.

Inspected by:

Name:Bülent GÜNDÜZGÖREN

Signature:

Date of issue:10.09.2015

Inspection centre: BV Turkey

**Checked by:**

Name: Gürbüz UZUN

Signature:

Distribution: ☒ CLIENT☐ MANUFACTURER☐☐